



Soundstation VTX 1000® Software Version 1.60.022 Release Notes

Date: June 23, 2006

Specific Release: SoundStation VTX 1000 software version 1.60.022

Subject: Release notes describing changes from Version 1.60.013 to 1.60.022.

Software Improvements/Bug Fixes

Audio

1. The SoundStation VTX 1000 automatically sent a wideband signature tone, even if phone was set to narrowband mode only. This has been fixed.
2. Line transmission audio will be muted when in HSSB bridged mode and in Hold state. This fix affects VTX -VSX bridge calls only.

UI

1. Changes to ensure VTX mute indications will match VSX, particularly when going from idle/on-hook (and muted) to off-hook/redial, or when receiving incoming VTX call while system is muted.
2. Corrected typographical errors in the Admin Setup title setup with passcode set and in menu numbering.
3. Allow ability to press “#” and “*” fast or simultaneously without causing issues
4. Ensure passcode key icon is present on all relevant screens.
5. Ensure diagnostic test speaker output continues if phone goes off-hook during test.

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>