


Internal USB version

rdx[®] QUIKSTOR Installation Guide




- 1 Turn off the computer
- 2 Mount the RDX QUIKSTOR in the PC. The Eject/Power LED should be on the lower right. Secure the unit by using the four mounting screws provided.
- 3 Connect the USB and power cables to the RDX QuikStor
- 4 Connect the USB cable to the host PC mother board or USB HBA. Pin 1 location is marked on the cable connector with a triangle (▼). Consult your motherboard/ HBA manual for the Pin 1 location on the mating USB connector
- 5 Turn on the computer



Warning:

- Connecting the USB Cable incorrectly to the PC will result in damage.
- Verify PIN layout on the motherboard versus cable connector PIN OUT.



Product Registration

Register this product at
www.tandbergdata.com/register

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>